ECS Configuration Change Request

CCR No. 96-0886	**Logged Date** 7/29/96	**Rev.** -	**Request Type** CCR

Priority Routine ☒ Urgent ☐ Emergency ☐	**Affected Release** I r 1	**Change Class** I I

Title Ir1 Version Description Document (VDD) Version 1.04.04, 8/14/96

Documents Affected Ir1 Version Description Document (VDD) for the ECS Project, 814-RD-004	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) or **Tech Reference** NCRs: ECSed02560

RTM Change   ☐   **Start New Baseline** ☐

Problem
The SGI Indigo2 system crashed while accessing the Exabyte tape drive.

Proposed Solution
This VDD documents the patches for SGI (Indigo2 system) with a Exabyte tape stacker (SCSI) attached
Machine this has been added to:
    SGI Indigo 2 (ICLG1SGI)
See NCR ECSed02560.

Impact Analysis:

Organizations Affected: BOO ☐   Contracts ☐   ESO ☐   FOS ☐   M&O ☒

QA ☒   Rel. A ☐   Rel. B ☐   Rel. IR1 ☒   MRS ☒   SMO ☒   Subconts ☐

A.1 ☐   Other _____

Cost:	None ☒	Small ☐ (Not exceeding $100,000)	Medium ☐ ($100,000 to $500,000)	Large ☐ (Over $500,000)

Schedule: None ☒   Other

Additional LOC _____   Man-Months _____

Materials

Originator James F. Ruckstuhl   (signed) James F. Ruckstuhl   8/14/96
                                         Signature   Date

Office SMO   Office Manager   (signed) Marc Bensimon   8/14/96
                                         Signature   Date

Disposition   Approved ☒   Approved w/Comment ☐   Forward ☐   Disapproved ☐

Comments:

CCB Chairperson   (signed)   Marc Bensimon   8/14/96
                         Signature   Date

CM01JU96   *ECS*